










897 N

72210



-  bolt or stud
-  hole
-  combination stud
-  air inlet
-  stud and nut

| | |
|--|---------------|
| Article status | Not Available |
| GTIN/EAN | 4054389114199 |
| Bellow number | 897 N |
|  kg | 1,9 kg |
|  | 10002725 |
|  | |

OE Manufacturer/Part No.

| Manufacturer | Original Part No. | Model |
|--------------|-------------------|-------|
| Cardi | 58050315 | |
| Scania | 411622 | |
| Dennis | 656 298/2 | |
| Pegaso | 794686 | 5231 |
| Pegaso | 795097 | 5231 |

| | | |
|--------|-----------|--------------|
| Scania | 411623 | BR 116 |
| Scania | 411623 | CR76 VA |
| LAG | | E 180 Z |
| LAG | | EOS |
| LAG | | Galaxy |
| Scania | 411623 | K 112 DR |
| Scania | 411623 | K 112 OR |
| Scania | 411623 | K 112 TR |
| Scania | 411623 | K 113 T |
| Scania | 411623 | K 113 TLA |
| Scania | 411623 | K 82-112 |
| Scania | 411623 | K 93 / K113 |
| Scania | 411623 | L 113 |
| Scania | 411623 | L 113 CLD |
| Scania | 411623 | L 92 / K 112 |
| Scania | 411623 | L 92 / K 113 |
| Scania | 411623 | N 113 C |
| LAG | | Panoramic |
| Dennis | 656 289/2 | Trident |